	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	0	"extrusion molding" and gear near5 puncture	USPAT; US-PGP UB; JPO	2004/08/22 10:24	
2	BRS	L2	0	"extrusion molding" and rotate near5 puncture	USPAT; US-PGP UB; JPO	2004/08/22 10:24	
3	BRS	L3	62	"extrusion molding" and rotate same (puncture or prick or hole)	USPAT; US-PGP UB; JPO	2004/08/22 10:34	
4	BRS	L4	4	("5219505" "5802442" "6101360" "6278858").PN.	USPAT	2004/08/22 10:32	
5	BRS	L5	8	"5618608"	USPAT; US-PGP UB; JPO	2004/08/22 10:35	
6	BRS	L6	7	5618608.URPN.	USPAT	2004/08/22 10:35	
7	BRS	L7	148	"weather strip" same holes	USPAT; US-PGP UB; JPO	2004/08/22 10:36	
8	BRS	L8	33	"weather strip" same holes and extrusion	USPAT; US-PGP UB; JPO	2004/08/22 10:38	
9	BRS	L9	2	"extrusion molding" same dimples	USPAT; US-PGP UB; JPO	2004/08/22 10:38	
10	BRS	L10	12	"extrusion molding" same puncture	USPAT; US-PGP UB; JPO	2004/08/22 10:39	
11	BRS	L11	76	"extrusion molding" and roller same (prick or puncture or hole or dimple)	USPAT; US-PGP UB; JPO	2004/08/22 10:39	

<u>..</u>-

~.~

	Error Definition	Err ors
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0
11		0